WITELLOFAX 1	Approved For Release 2002/08/14 : @ <u>A-RDP82-00457R01170028000</u> 8-8	25X1 25X
TOPIC	Zaten-Post ol contro Asias al d	NTERN HIBER BOX (DELTA)
10110 estera terroritaria estera en constituira en	THE COLUMN TO SECTION AND THE PARTY OF THE P	LAMPACA SAFAK
EVALUATION	25X1 PLACE OBTAINED	25X
DATE OF CONTEN	October 1950 to 15 November 1951	networks was been a supple
DATE OBTAINED_	DATE PREPARED 9 ADM11 1952 25X1	
	ENCLOSURES (No. & Type) 1 - one sketch on ditto	
F V In 1777 UV V V V Amptitument angerer		CTRANSE II A MININE PROCESSA
interviewe in the second s		ining State decorations
CHARLES THE MONTH OF REPORT THE CHARLES AND THE SECURIOR AND THE SECURIOR S		in we all of the contribute and a size who
menne till skriveringsprover i til der britisk for det skrivering begott i det et s	SHATE SHEET STORES AND TOTAL SHEET OF THE SHEET OF THE ACT OF THE	25×
SOURCE		
J.o	In October 1950, about 250 workers of the Konstruktiva branch of the CSSZ were employed at the Zatec-Postoloprty (N 51/F 21) airfield. The chief construction supervisor was Cech (fmu). The lst Co of the 6361st Technical Auxiliary Bn (PIP) in Hvezdov (0 51/F 95) and 400 volunteers from various military units also did construction work at the field.	
2.	The two runways available at the field were built by the personnel of the PTP battalion. One of these runways, the shorter of the two, which was about 800 x 200 meters, was in the middle of the field. During construction, the earth was excavated to the depth of 60 cm by means of seven bulldozers. The subgrade was formed by a 20-cm layer of broken stones, followed by a 10-cm layer of broken stones of a finer grade mixed with sand. The second layer was topped by a 30-cm concrete surface provided with expansion joints spaced at about four meter intervals and filled with asphalt. The second runway, which ran parallel to the first and about 600 meters to the south, was about 1,200 x 300 meters and was constructed in the same way as the other runway. In October 1950, only its eastern third was completed. The runways were well drained by four drainage canals leading from the runways to the northeast where they terminated in a main drainage canal consisting of reinforced concrete pipes 220 cm in diameter. The main drainage canal crossed the Postoloprty-Vysocany (N 51/F 11) road and joined the Chomutovka brook near Tatina (N 51/F 11). In October 1951, work on the construction of a lane connecting the two runways was begun.	
3.		

80 x 30 meters northwest of the field which housed the offices of the Konstruktiva building enterprise; a single-story brick building about 100 x 50 meters housing the PX shop for civilian and military personnel at the field; 10 low wooden buildings serving as quarters for the air-field construction workers; a single-story building occupied since

	Approved For Releas <u>e 2002/08/14 : CIA-RDP82-0045</u> 7R011700280008-8	
	S COMMITTA HACAMATION COMMITTAL	2 5 31
	building with an observation tower about 15 meters high on which four spot- lights were placed; and quarters for the guards. A spur track ran from Postoloprty to the northern edge of the field. *	
lto	Source never saw aircraft at the field. Occasionally, sedans occupied by Czech and Soviet officers, who apparently inspected the progress of the construction work, arrived at the installation. The field was strictly guarded and access was only permitted to persons carrying a pass of the Konstruktiva building enterprise. **	
**	Comment. For layout sketch of the field, see Annex. The four underground installations are believed to be storage facilities for amounition or fuel. Comment. The present report in conjunction with previous information furnishes a good picture of the status of the field. However, it is believed that the length of the two runways at the field was underestimated, while their width was exaggerated. The northern runway was	25X1
	mentioned already in a report dating from September 1918 and it is believed to have been in existence at the end of the war, but the other runway was not built before 1950 or 1951. The latter runway probably meets modern requirements. It is assumed that the northern runway is chiefly used for the parking and servicing of aircraft, as the soil of the field appears to be rather soft. The arrival, in September 1951, of air force soldiers indicates that the installation may be ready for occupation in 1952.	

25X1

25X1

25X1

CONFEDERATION SHORRITY TEFORMATION

Legend:

- 1. Short runway.
- 2. Long runway.
- 3. Concrete road.
- 4. Concrete road under construction.
- 5. Hangar.
- 6. Drainage canal.
- 7. Office of the Konstruktiva building enterprise.
- 8. Yess hall for military and civilian workers.
- 9. About 5 low wooden buildings, quarters for construction workers.
- 10. About 5 low wooden buildings, quartering facilities for a military labor detail.
- 11. Quarters for air force personnel.
- 12. Underground fuel tanks, filling station for vehicles.
- 13. Houses under construction.
- li. Underground installations with iron doors.
- 15. Houses under construction.
- 16. Quarters for guard personnel.
- 17. Main guardhouse with observation tower.
- 13. Spur track to the Postoloprty railroad station.
- 19. Temporary spur track.

COMPIDMENTAL/

25X1

